Table of Contents

Introduction **1**

1 Preparation techniques for diamond-like carbon **5**

1.1 Diamond-like Carbon films 5

1.2 Nomenclature 7

1.3 Deposition Techniques 10

1.3.1 Sputter-deposited a-C *12*

1.3.2 PACVD deposited a-C:H *13*

2 Characterization of a-C and a-C:H films **14**

2.1 Preparation of the substrates before depositing DLC films 14

2.2 Thickness measurement 15

2.3 Deposition rate and roughness 15

2.4 Hardness and hydrogen percentage 16

2.5 Optical experimental technique 19

2.5.1 Optical Constants *20*

2.5.2 Ellipsometry on a-C and a-C:H films *21*

2.6.1 Raman spectroscopy experimental technique *32*

2.6.2 Raman spectroscopy on DLC *33*

2.7 Resistivity/conductivity measurement 36

2.7.1 Four-point probe *37*

2.8 van der Pauw measurements 40

2.8.1 Low temperature current transport mechanism *43*

2.8.2 I-V measurements *47*

2.9 Conclusions 62

3 Gauge factor measurements of a-C films **63**

3.1 Basic mechanics 63

3.2 Cantilever principle for measuring piezoresistive effect in DLC 66

3.3 Micromachining techniques 68

3.3.1 Wafer cleaning *68*

3.3.2 Thermal Oxidation *69*

3.3.3 Diffusion *69*

3.3.4 Lithography *69*

3.3.5 Etching *70*

3.4 Fabrication of cantilever 70

3.5 Set-up for cantilever measurement 73

3.6 Results on the cantilever 75

3.7 Boss membrane principle 81

3.8 Fabrication of boss membrane with a-C films on it 85

3.9 Set-up for gauge factor measurements on boss membrane 87
3.10 Modeling of the boss membrane 88
3.11 Results on the boss membrane 91

4 Gauge factor measurements of a-C:H films 94

4.1 First design of the boss membrane and results on it 94
4.1.1 Problems with the first test structure 100
4.2 Modified boss membrane test structure and corresponding results 100
4.2.1 Fabrication of modified test structure 101
4.3 Gauge factor measurements at elevated temperatures 112
4.4 Longitudinal gauge factor measurements 113
4.5 Longitudinal and transversal finger-like structures 117

5 Discussions 121

5.1 Origin of the piezoresistive effect in DLC 121
5.2 Summary of gauge factor results and error analysis 125

Abbreviations and acronyms 132

Symbols 135

References 138

Publications 152