

Contents

Abstract	iii
Outline of the Thesis	iv
Contribution of this Work	vi
List of Abbreviations	vii
Contents	ix
I Principle of Operation	1
1 Introduction	2
1.1 Problem Statement	3
2 System Concept	4
II Theoretical and Practical Background	6
3 Panoramic Imaging	7
3.1 Image Registration using Normalized Phase Correlation	7
3.2 Automatic Image Cut and Paste	8
3.3 Examples for Panoramic Imaging	9
3.3.1 Ladle	9
3.3.2 Converter	11
3.3.3 Laboratory Setup	13
4 Panoramic Stereo Imaging	14
4.1 Panoramic Stereo	14
4.2 Circular Projections	15
4.3 Omnistereore with a Rotating Camera	16
4.3.1 Stereo Mosaicing with a Slit Camera	16
4.3.2 Stereo Mosaicing with a “Simulated” Slit Camera	17
4.4 Displaying Stereo Panoramas	18
4.4.1 Setup of a Stereo Panorama to be viewed with Anaglyph Glasses	19
4.5 Examples for Omnistereore Imaging	19
4.5.1 Simulated Ladle Surface captured with a 4.5 mm Lens	19
4.5.2 Workpiece captured with a 25 mm Lens	22
4.5.3 Simulated Ladle Surface captured with a 12.5 mm Lens	23

5	Panoramic Optical Servoing	25
5.1	Generation of a Panoramic Map	26
5.1.1	Example for the Generation of a Panoramic Map	26
5.2	The Human Machine Interface (HMI)	27
5.2.1	Example for Panoramic Optical Servoing	29
6	High Temperature Imaging	31
6.1	Development of a High Temperature Measurement System	33
6.1.1	Selection of the Data Transmission	35
6.1.2	Selection of the Camera	36
6.1.3	Selection of the Lens	38
6.1.4	Selection of Heat Protecting Glasses and Hot Mirrors	40
6.1.5	Thermal Radiation of a Solid Body	41
6.1.6	Selection of a Heat Protecting Housing	47
6.2	Presentation of the Industrial Solution	47
III	Applications	49
7	Laboratory Measurements	50
7.1	Structured Analysis, Design and Programming	51
7.2	The Laboratory Setup	52
7.3	Proof of the System Concept using the Laboratory Setup	54
7.3.1	Conclusion	57
8	High Temperature Measurements	58
8.1	Measurements in a Ladle at 1100°C	59
8.1.1	The High Temperature Measurement Test System	59
8.1.2	High Temperature Measurements in the Ladle at 1100°C	62
8.1.3	Conclusion	64
8.2	Measurements in an Oven at 1600°C	66
8.2.1	The Modified High Temperature Measurement Test System	66
8.2.2	High Temperature Measurements in an Oven at 1600°C	68
8.2.3	Conclusion	72
8.3	Measurements in a Converter at 1400°C	74
8.3.1	Test of the Industrial Prototype	74
8.3.2	High Temperature Measurements in a Converter at 1400°C	76
8.3.3	Conclusion	83
9	Conclusion and Future Work	84
	Authors Publications	86
	Publications	86
	Oral Presentations	87
	Reports	87
	List of Figures	90
	Bibliography	96
	Index	97