

# Content

<b>Preface</b> .....	<b>i</b>
<b>List of Symbols</b> .....	<b>v</b>
<b>1 Fundamentals of Grain Boundaries and Triple Lines</b> .....	<b>1</b>
1.1 Introduction .....	1
1.2 Grain boundaries .....	2
1.2.1 Grain boundary structure.....	2
1.2.2 Grain boundary energy .....	8
1.3 Grain boundary thermal grooving .....	10
1.3.1 Formation of a grain boundary thermal groove.....	10
1.3.2 Investigations of grain boundary thermal grooves .....	15
1.4 Grain boundary triple line .....	17
1.4.1 Overview on triple lines .....	17
1.4.2 Investigations on triple line energy .....	20
<b>2 Experimental Setup</b> .....	<b>23</b>
2.1 Introduction .....	23
2.2 Specimen preparations.....	24
2.2.1 Fabrication of the single and tricrystals.....	24
2.2.2 Characterization of the crystal orientations .....	27
2.2.3 Preparation of the specimens.....	28
2.3 Investigations.....	30
2.3.1 Atomic force microscopy .....	30
2.3.2 Influence of the tip .....	32
2.3.3 Analysis of the images .....	37

<b>3 Grain Boundary-Free Surface Line Tension .....</b>	<b>41</b>
3.1 Introduction .....	41
3.2 Grain boundary energy measurement.....	43
3.2.1 Grain boundary energy in polycrystals.....	43
3.2.2 Specific grain boundary energy.....	45
3.3 Grain boundary-free surface line tension on bicrystals .....	48
3.3.1 Line tension of random grain boundary groove root.....	48
3.3.2 Line tension of specific grain boundary groove root.....	49
3.4 Grain boundary-free surface line tension on nanowires .....	52
3.4.1 Fabrication of copper nanowires .....	52
3.4.2 Groove root line tension of copper nanowires.....	53
3.5 Effect of grain boundary-free surface line tension on the Gibbs- Thompson relation.....	55
<b>4 Grain Boundary Triple Line Energy .....</b>	<b>59</b>
4.1 Introduction .....	59
4.2 Grain boundary triple line energy in copper.....	60
4.2.1 Triple line energy in copper polycrystals .....	60
4.2.2 Triple line energy in copper tricrystals.....	63
4.3 Triple line energy in solids .....	69
4.3.1 Effect of triple line energy on grain growth .....	69
4.3.2 Effect of triple line energy on the Zener force .....	73
<b>5 Discussion.....</b>	<b>79</b>
5.1 Grain boundary-free surface line tension .....	79
5.2 Grain boundary triple line energy.....	81
<b>6 Summary.....</b>	<b>85</b>
<b>Zusammenfassung.....</b>	<b>87</b>
<b>References .....</b>	<b>89</b>
<b>Appendix A .....</b>	<b>97</b>