




Maria Bostenaru Dan (Autor)
Housing in Bucharest, Romania
An Analysis of Vulnerability to Earthquakes



<https://cuvillier.de/de/shop/publications/762>

Copyright:
Cuvillier Verlag, Inhaberin Annette Jentsch-Cuvillier, Nonnenstieg 8, 37075 Göttingen,
Germany
Telefon: +49 (0)551 54724-0, E-Mail: info@cuvillier.de, Website: <https://cuvillier.de>

CONTENTS

Acknowledgements	8
Introduction: The built substance of Bucharest	9
2. Site survey	14
2.1. Mapping the impact	15
2.2. Surveyed characteristics	16
3. Typological survey	18
Before 1850:	35
Eclecticism:	36
One family one storey house, also called "wagon house" (#85)	37
General Information	38
Architectural features	39
Socio-economic issues	41
Structural features	44
Evaluation of Seismic Performance and Seismic Vulnerability	49
Earthquake Damage Patterns	55
Building Materials and Construction Process	56
Construction Economics	64
Insurance	66
Seismic Strengthening Technologies	66
Pictures	75
Romanian Art Nouveau:	96
A single-family, two-storey house with brick walls and timber floors (#84)	98
General Information	99
Architectural Features	100
Socio-Economic Issues	102
Structural Features	104
Evaluation of Seismic Performance and Seismic Vulnerability	107
Earthquake Damage Patterns	112
Building Materials and Construction Process	112
Construction Economics	116
Insurance	116
Seismic Strengthening Technologies	116
Pictures	121
Multistorey masonry house	131
General Information	131
Architectural Features	132

Socio-Economic Issues	134
Structural Features	136
Evaluation of Seismic Performance and Seismic Vulnerability	138
Earthquake Damage Patterns	142
Building Materials and Construction Process	143
Construction Economics	146
Insurance	146
Seismic Strengthening Technologies	146
Pictures	150
Romanian Avant-Garde:	155
Early reinforced concrete frame condominium building with masonry infill walls designed for gravity loads only (#96)	156
General Information	157
Architectural Features	159
Socio-Economic Issues	161
Structural Features	164
Evaluation of Seismic Performance and Seismic Vulnerability	173
Earthquake Damage Patterns	180
Building Materials and Construction Process	183
Construction economics	198
Insurance	200
Seismic Strengthening Technologies	201
Pictures	209
Building of the Modern Movement - with commercial ground floor	225
General Information	227
Architectural Features	228
Socio-Economic Issues	229
Structural Features	232
Evaluation of Seismic Performance and Seismic Vulnerability	237
Earthquake Damage Patterns	243
Building Materials and Construction Process	246
Construction economics	254
Insurance	256
Seismic Strengthening Technologies	256
Pictures	264
1940-1950:	278
Reinforced concrete frame structure with diagonal bracings and brick infill walls (#71)	279

General Information	280
Architectural Features	281
Socio-Economic Issues	282
Structural features	284
Evaluation of Seismic Performance and Seismic Vulnerability	286
Earthquake Damage Patterns	290
Building Materials and Construction Process	290
Construction Economics	295
Insurance	295
Seismic Strengthening Technologies	295
Pictures	299
International Style (1945-1977):	309
Reinforced concrete cast-in situ shear wall buildings ("OD"-type, with "fagure" plan) (#78).....	310
General Information	311
Architectural Features	312
Socio-Economic Issues	313
Structural Features	315
Evaluation of Seismic Performance and Seismic Vulnerability	318
Earthquake Damage Patterns	323
Building Materials and Construction Process	323
Construction Economics	327
Insurance	327
Seismic Strengthening Technologies	327
Pictures	331
Block of flats with 11 floors out of cast-in-situ concrete, gliding frameworks (#87).....	339
General Information	340
Architectural Features	341
Socio-Economic Issues	342
Structural Features	345
Evaluation of Seismic Performance and Seismic Vulnerability	347
Earthquake Damage Patterns	352
Building Materials and Construction Process	353
Construction Economics	357
Insurance	358
Seismic Strengthening Technologies	358
Pictures:	362

Romanian Socialist Architecture (1977-1990):	379
Precast concrete panel apartment buildings (#83)	380
General Information	381
Architectural Features	382
Socio-Economic Issues	383
Structural Features	386
Evaluation of Seismic Performance and Seismic	
Vulnerability	389
Earthquake Damage Patterns	393
Building Materials and Construction Process	394
Construction Economics	397
Insurance	397
Seismic Strengthening Technologies	397
Pictures:	399
Contemporary styles:	405
Medium/high rise moment resisting reinforced concrete frame	
buildings (#97).....	406
General Information	406
Architectural Features	407
Socio-Economic Issues	409
Structural Features	411
Evaluation of Seismic Performance and Seismic	
Vulnerability	413
Earthquake Damage Patterns	418
Building Materials and Construction Process	419
Construction Economics	423
Insurance	424
Seismic Strengthening Technologies	424
Pictures:	427
CV	450